


CONNECT GRAY
WIRE TO
TACHOMETER IF
NEEDED

NOT USED IN THIS
APPLICATION


REV LIMITER
NOT USED ON THIS
APPLICATION




DISCONNECT FACTORY HARNESS FROM
COIL AND CONNECT TO MSD RED & WHITE
WIRES

CONNECT MSD ORANGE & BLACK WIRES TO
COIL

USE TERMINALS AND CONNECTOR
PROVIDED



COIL



CONNECT BLACK WIRE TO
GROUND & RED WIRE TO B+

| | |
|--------------------------|-----------------------|
| MSD | |
| WHIPPLE MSD INSTRUCTIONS | |
| WHIPPLE IND | |
| REVISION 04/21/04 | SCALE = NOT TO SCALE |
| FILE NAME | MSD CONNECTIONS1A.YSD |