



CONNECT GRAY
WIRE TO
TACHOMETER IF
NEEDED

NOT USED IN THIS
APPLICATION


REV LIMITER
NOT USED ON THIS
APPLICATION



DISCONNECT FACTORY HARNESS FROM
COIL AND CONNECT TO MSD RED & WHITE
WIRES

CONNECT MSD ORANGE & BLACK WIRES TO
COIL

USE TERMINALS AND CONNECTOR
PROVIDED



MSD	
WHIPPLE MSD INSTRUCTIONS	
WHIPPLE IND	
REVISION 04/21/04	SCALE = NOT TO SCALE
FILE NAME	MSD CONNECTIONS1A.YSD